

# Oil Field Environmental Incident Summary

**Incident:** 20150311191524      **Date/Time of Notice:** 03/11/2015 19:15

**Responsible Party:** FRONTIER VENTURES, LLC

**Well Operator:** FRONTIER VENTURES, LLC

**Well Name:** KRABSETH 1

**Field Name:** WINNER

**Well File #:** 90199

**Date Incident:** 3/10/2015

**Time Incident:** 22:00

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 158

**Rng:** 100

**Sec:** 24

**Qtr:**

**Location Description:**

**Submitted By:** Dean Throntveit

**Received By:**

**Contact Person:** Dean Throntveit  
PO BOX 717  
CROSBY, ND 58730

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 1320 Feet

**Distance Nearest Water Well:** 400 Feet

**Type of Incident** Tank Overflow

**Release Contained in Dike** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	30	Barrels	30	Barrels		
<b>Brine</b>	30	Barrels	30	Barrels		

**Other**

**Description of Other Released Contaminant:**

N/A

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

None

**Areal Extent:**

n/a

**Potential Environmental Impacts:**

None

**Action Taken or Planned:**

corrected valve position, spilled oil water sucked up    Retrain staff on proper procedures for day to day operations

**Wastes Disposal Location:** 13 mile solid waste disposal ( secure)

**Agencies Involved:**

**Updates**

**Date:** 3/12/2015

**Status:** Reviewed; O&G Lead

**Staff:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill remained on location. NDIC retains oversight.